



Telephone: 386-937-2615
Website: www.vesselfinders.com

Fax-Phone: 828-516-2227
E-mail: larry@vesselfinders.com

Vessel Information Sheet

File #:	2492FT	Type	Pole & Line Fishing	Price	\$425,000.00 USD
<u>Description:</u>					
Year Built	1979	Builder	USA	Construction:	Welded Aluminum
Length (LOA)	83'	Registered length	78'	Beam	23'
Draft		Loaded draft		Depth	11.6'
Gross Tons	98	Net Tons	66	DWT	
Vessel Location	Pacific Northwest USA	Flag	USA	Class	
Certified		Pass: Qty		Date Exp.	
<u>Capacities</u>					
Fuel	21,000 gallons	Potable Water	1,800 gallons	Ballast	
Cargo fuel:		Other:			
Misc:					
<u>Machinery:</u>					
Engine:	Detroit Diesels Series 60	Count:	2	HP:	400 hp each
Engine hours:				Consumption	4.7gph fishing/7.1 gph running
Gear model:	Twin Disc	Ratio:	6:01	Prop dia:	60" x 46" Four Blade
Nozzle:		Speed		Bollard Pull	
Bow Thruster:		HP		DP	
Generator:	John Deere	Qty	2	KW	40 kw
Gen other:		Qty		KW	



Telephone: 386-937-2615
Website: www.vesselfinders.com

Fax-Phone: 828-516-2227
E-mail: larry@vesselfinders.com

Vessel Information Sheet

File #: **2492FT** **Type** Pole & Line Fishing **Price** **\$425,000.00 USD**

Fishing Equipment:

Top Fish Freezer: 20' container mounted on deck **Hold:** 11 Tons
Main Fish Hold: Fully insulated **Hold:** 63 Tons cooled by 8 air blast freezer evaporators w/21" fans
Refrigeration: (2) Freezer systems in lower hold provide enough freezing capacity to handle any load (evaporator temps around -45°)

Electronics & Safety:

VHF Radio	Standard Horizon	SSB:	ICOM	EPIRB:	Yes
Depth Sounder:	Furuno	Gyro:		Compass:	Furuno
Radar:	Furuno	Auto Pilot:	COMNAV	AIS:	COMNAV
GPS:	Furuno	Plotter:	SITEX	Safety	Yes

Deck:

Clear Deck:	Deck strength:	Certified tons:
Liferaft:	Dimensions	Ramp capacity
Anchor winch:	Deck winches:	Cranes

Accommodations:

Staterooms:	2	Berths:	6	Galley:	Yes	Air/Heat:	Yes
--------------------	---	----------------	---	----------------	-----	------------------	-----

Comments:

Hull bottom has a three-layer epoxy barrier coat. Latch dogs on the Fo'c'sle hatch were replaced & the hole for the shore power cord was sealed as per past survey recommendation.

All details above are given in good faith, without guarantee, from information received from owners and/or owners' agents.